

ASSEMBLY INSTRUCTIONS

WEOS12

CABINET PARTS LIST


B-Side Panels(1) B1 little side panels C-Top panel D-Botton Panels

F-Shelf(2)


HARDWARE PARTS LIST

3-Screw(Φ 3.5*25-20)


Step1:




Step2:




Step3:




Step4:



Step5:



Step6:



Step7:

